

RDO-CAP-1

Replacement DO Sensor Cap

Replacement Sensor Cap for MX800 Series DO Sensor (W-DO)



Replaces the original DO sensor cap provided with DO sensors (W-DO). These caps have a 2-year cap life and will continue to operate after that, but possibly with reduced accuracy.

Contact Us

Sales (8am to 5pm ET, Monday through Friday)

- Email sales@onsetcomp.com
- Call 1-508-759-9500
- In U.S. toll free 1-800-564-4377
- Fax 1-508-759-9100

Technical Support (8am to 5pm ET, Monday through Friday)

- Contact Product Support www.onsetcomp.com/support/contact
- Call 1-508-759-9500
- In U.S. toll free 1-877-564-4377

Onset Computer Corporation
470 MacArthur Boulevard
Bourne, MA 02532

