

HUM-RHPCB-3

## Replacement RH Sensor for U14-001


(for U14-001s with serial #s below 9847173)

Discontinued

Replacement RH Sensor for U14-001 (with serial #s below 9847173)

### Important Information

For U14-001s with serial numbers above 9847173 - please see part # HUM-RHCP-3A



### Contact Us

Sales (8am to 5pm ET, Monday through Friday)

- Email [sales@onsetcomp.com](mailto:sales@onsetcomp.com)
- Call 1-508-759-9500
- In U.S. toll free 1-800-564-4377
- Fax 1-508-759-9100

Technical Support (8am to 5pm ET, Monday through Friday)

- Contact Product Support [www.onsetcomp.com/support/contact](http://www.onsetcomp.com/support/contact)
- Call 1-508-759-9500
- In U.S. toll free 1-877-564-4377

Onset Computer Corporation  
470 MacArthur Boulevard  
Bourne, MA 02532

