


## Wiring Diagram

AC-SENS-1 12V 400mA sensor AC power adapter



Polarity is very important - there is a bold white (broken) stripe marking the positive lead. The negative lead has no stripe and only has tiny lettering.

Positive (+) bold white (broken) stripe marking  
Negative (-) no stripe and has tiny lettering

