

## Wiring Diagram

HOBO® RX3000  
Remote Monitoring System  
Monitoring:  
• Temperature (15)

The total cumulative sensor cable length (including any extension cables that may be used) cannot exceed 100-meters (328-feet)

