



HOBO[®] CABLE-CO2

Sensor output cable

CO2 Sensor to Logger Cable (20.3cm - 8 inches) for use with HOBO Analog data loggers.



Key Advantages:

- Plug directly into the external input jacks to expand the range of measurement options and applications

Contact Us

Sales (8am to 5pm ET, Monday through Friday)

- ▶ Email sales@onsetcomp.com
- ▶ Call 1-508-759-9500
- ▶ In U.S. toll free 1-800-564-4377
- ▶ Fax 1-508-759-9100

Technical Support (8am to 6pm ET, Monday through Friday)

- ▶ Contact Product Support www.onsetcomp.com/support/contact
- ▶ Call 1-508-759-9500
- ▶ In U.S. toll free 1-877-564-4377

Onset Computer Corporation
470 MacArthur Boulevard
Bourne, MA 02532